

Machine format: Tajima

Color changes: 18

Stops: 19

Trims: 32

Appliqués: 0

Left: 40.4 mm

Right: 40.4 mm

Up: 40.4 mm

Down: 40.4 mm

EndX: 0.0 mm

EndY: 0.0 mm

Area 6528.6 mm²

Max stitch: 11.8 mm

Min stitch: 0.0 mm

Max jump: 6.7 mm












Total thread: 105.44m








Total bobbin: 37.94m

Stop Sequence:

#	N#	Color	St.	Code	Name	Chart
1.	1		10,510	61001		Gunold Poly40
2.	33		3,473	61511		Gunold Poly40
3.	32		983	61910		Gunold Poly40
4.	1		486	61001		Gunold Poly40
5.	6		1,507	61181		Gunold Poly40
6.	1		240	61001		Gunold Poly40
7.	33		134	61511		Gunold Poly40
8.	1		243	61001		Gunold Poly40
9.	33		138	61511		Gunold Poly40
10.	1		293	61001		Gunold Poly40
11.	33		175	61511		Gunold Poly40
12.	1		243	61001		Gunold Poly40
13.	33		137	61511		Gunold Poly40
14.	1		324	61001		Gunold Poly40
15.	33		198	61511		Gunold Poly40
16.	1		237	61001		Gunold Poly40
17.	33		150	61511		Gunold Poly40
18.	1		181	61001		Gunold Poly40
19.	33		107	61511		Gunold Poly40



			
Stop #: 1 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 10,510 Thread used: 63.81m	Stop #: 2 Element: Code: 61511 Name: Chart: Gunold Poly40 Stitches: 3,473 Thread used: 16.13m	Stop #: 3 Element: Code: 61910 Name: Chart: Gunold Poly40 Stitches: 983 Thread used: 3.91m	Stop #: 4 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 486 Thread used: 2.20m
			
Stop #: 5 Element: Code: 61181 Name: Chart: Gunold Poly40 Stitches: 1,507 Thread used: 6.24m	Stop #: 6 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 240 Thread used: 1.07m	Stop #: 7 Element: Code: 61511 Name: Chart: Gunold Poly40 Stitches: 134 Thread used: 0.47m	Stop #: 8 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 243 Thread used: 1.08m
			
Stop #: 9 Element: Code: 61511 Name: Chart: Gunold Poly40 Stitches: 138 Thread used: 0.48m	Stop #: 10 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 293 Thread used: 1.30m	Stop #: 11 Element: Code: 61511 Name: Chart: Gunold Poly40 Stitches: 175 Thread used: 0.59m	Stop #: 12 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 243 Thread used: 1.09m

 Stop #: 13 Element: Code: 61511 Name: Chart: Gunold Poly40 Stitches: 137 Thread used: 0.48m	 Stop #: 14 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 324 Thread used: 1.34m	 Stop #: 15 Element: Code: 61511 Name: Chart: Gunold Poly40 Stitches: 198 Thread used: 0.64m	 Stop #: 16 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 237 Thread used: 1.04m
 Stop #: 17 Element: Code: 61511 Name: Chart: Gunold Poly40 Stitches: 150 Thread used: 0.50m	 Stop #: 18 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 181 Thread used: 0.81m	 Stop #: 19 Element: Code: 61511 Name: Chart: Gunold Poly40 Stitches: 107 Thread used: 0.36m	