

Machine format: Tajima

Color changes: 20

Stops: 21

Trims: 50

Appliqués: 0

Left: 40.2 mm

Right: 40.2 mm

Up: 40.2 mm

Down: 40.2 mm

EndX: 0.0 mm

EndY: 0.0 mm

Area 6456.6 mm²

Max stitch: 10.7 mm

Min stitch: 0.0 mm

Max jump: 6.6 mm











Total thread: 114.95m










Total bobbin: 39.85m

Stop Sequence:

#	N#	Color	St.	Code	Name	Chart
1.	25		6,250	61508		Gunold Poly40
2.	1		4,510	61001		Gunold Poly40
3.	2		6,958	61109		Gunold Poly40
4.	25		497	61508		Gunold Poly40
5.	2		249	61109		Gunold Poly40
6.	25		264	61508		Gunold Poly40
7.	2		126	61109		Gunold Poly40
8.	25		342	61508		Gunold Poly40
9.	2		201	61109		Gunold Poly40
10.	1		911	61001		Gunold Poly40
11.	2		273	61109		Gunold Poly40
12.	1		358	61001		Gunold Poly40
13.	2		206	61109		Gunold Poly40
14.	1		259	61001		Gunold Poly40
15.	2		126	61109		Gunold Poly40
16.	1		252	61001		Gunold Poly40
17.	2		153	61109		Gunold Poly40
18.	1		297	61001		Gunold Poly40
19.	2		165	61109		Gunold Poly40
20.	1		251	61001		Gunold Poly40
21.	2		156	61109		Gunold Poly40



			
Stop #: 1 Element: Code: 61508 Name: Chart: Gunold Poly40 Stitches: 6,250 Thread used: 35.54m	Stop #: 2 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 4,510 Thread used: 28.98m	Stop #: 3 Element: Code: 61109 Name: Chart: Gunold Poly40 Stitches: 6,958 Thread used: 27.63m	Stop #: 4 Element: Code: 61508 Name: Chart: Gunold Poly40 Stitches: 497 Thread used: 2.20m
			
Stop #: 5 Element: Code: 61109 Name: Chart: Gunold Poly40 Stitches: 249 Thread used: 0.81m	Stop #: 6 Element: Code: 61508 Name: Chart: Gunold Poly40 Stitches: 264 Thread used: 1.21m	Stop #: 7 Element: Code: 61109 Name: Chart: Gunold Poly40 Stitches: 126 Thread used: 0.45m	Stop #: 8 Element: Code: 61508 Name: Chart: Gunold Poly40 Stitches: 342 Thread used: 1.55m
			
Stop #: 9 Element: Code: 61109 Name: Chart: Gunold Poly40 Stitches: 201 Thread used: 0.67m	Stop #: 10 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 911 Thread used: 3.95m	Stop #: 11 Element: Code: 61109 Name: Chart: Gunold Poly40 Stitches: 273 Thread used: 0.87m	Stop #: 12 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 358 Thread used: 1.58m

			
Stop #: 13 Element: Code: 61109 Name: Chart: Gunold Poly40 Stitches: 206 Thread used: 0.71m	Stop #: 14 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 259 Thread used: 1.12m	Stop #: 15 Element: Code: 61109 Name: Chart: Gunold Poly40 Stitches: 126 Thread used: 0.45m	Stop #: 16 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 252 Thread used: 1.12m
			
Stop #: 17 Element: Code: 61109 Name: Chart: Gunold Poly40 Stitches: 153 Thread used: 0.53m	Stop #: 18 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 297 Thread used: 1.29m	Stop #: 19 Element: Code: 61109 Name: Chart: Gunold Poly40 Stitches: 165 Thread used: 0.55m	Stop #: 20 Element: Code: 61001 Name: Chart: Gunold Poly40 Stitches: 251 Thread used: 1.12m
			
Stop #: 21 Element: Code: 61109 Name: Chart: Gunold Poly40 Stitches: 156 Thread used: 0.53m			